



RGE/Geotechnical Engineering 註冊岩土工程師/岩土工程

- **Rock Mapping, Tunnel Mapping, Boulder Survey, Aerial Photo Interpretation (API)**
- 地質勘察、隧道地質評估、孤石安全評估、航空照片判釋
- **Natural Terrain Hazard Study (NTHS)**
- 天然山坡災害評估
- **Dangerous Hillside Order (DHO)**
- 危險斜坡令
- **Engineering Inspection for Slopes**
- 斜坡檢查

Some Projects as Example

部分項目例子

CLP Black Point Power Station, Lung Kwu Tan	中電龍鼓灘發電廠
Geotechnical Assessment for A&A Works at 1 Shouson Hill Road East	壽臣山東路 1 號加改建工程岩土評估
Airport Authority Contract P560(R) Aviation Fuel Pipeline Diversion – Natural Terrain Hazard Study	機場管理局合約 P560(R) 航空油管改道 - 天然山坡災害評估
Dangerous Hillside Order – Tin Shui Wai “Earth Mount”	危險斜坡令 - 天水圍“泥頭山”
Dangerous Hillside Order – 44 Kung Lok Road	危險斜坡令 - 功樂道 44 號功樂大廈
Emergency Slope Stabilisation & Investigation after Landslip – 23 Stanley Village Road	緊急斜坡鞏固及調查山泥傾斜 - 赤柱村道 23 號
Emergency Investigation & Stabilisation – Rehabus Parking at Pokfulam Road	緊急地陷調查及鞏固 - 薄扶林道康復巴士停車場
Slope Remedial Works & Rock Slope Mapping at Manson Industrial Bldg, A Kung Ngam Village Rd	阿公岩村道民興工業大廈斜坡鞏固工程及石坡勘察
WSD Proposed Desalination Plant at TKO Area 137 Boulder and Rock Slope Surveys	水務署擬建海水化淡廠將軍澳 137 區孤石及石坡安全評估
CEDD Development of Anderson Road Quarry Site - Flexible Barrier System Geotechnical Supervision	土木工程署安達臣礦場發展 - 柔韌護欄系統岩土監督
CEDD LPM at back of Queen Marry Hospital - Flexible Barrier System Geotechnical Supervision	土木工程署山泥傾瀉防治工程瑪麗醫院山邊- 柔韌護欄系統岩土監督
Road Widening for Harrow International School – Rock Mapping & Geotechnical Inspection	哈羅香港國際學校道路擴闊 - 石坡勘察及岩土檢測
Development at 5 Fei Ngo Shan Rd Rock Mapping	飛鵝山道 5 號發展石坡勘察
Claim Consultant for Site Formation accident at RBL1168 South Bay Road	南灣路 RBL1168 地盆平整工程意外索賠顧問
Site Formation of number of NT Exempted Houses	多間新界豁免屋宇地盆平整
Engineering Inspection (EI) of Slopes :	斜坡檢查 :
Tsing Ma Control Area (from Tsing Yi to Lantau), over 200 no. slopes	青馬管制區(由青衣至大嶼山), 超過 200 個斜坡
Wilshire Tower, 200 Tin Hau Temple Road	天后廟道 200 號慧雅閣
Fulrich Garden, 9 Kung Lok Rd, Kwun Tong	官塘功樂道 9 號富麗花園